

Team Industrial Services

Concrete Repair Services (CRS)



A spalled floor being injected with epoxy prior to repair.

A leaking concrete tank (above) can create problems for a facility.

Team utilizes state-of-the-art materials, repair methods, tools and trained technicians to repair and restore your concrete structures; making them as good as – and often better than – new.

History

- Established in 1985
- Available through all Team service centers

Repair services available

- Urethane crack injection
- Epoxy injection
- Expansion joints
- Coatings/toppings
- Spall repair
- Pump base repairs
- Secondary containments

Urethane crack injection

- Seals cracks, leaks
- Team's CR-5A hydrophobic sealant utilized onsite
 - Excellent bonding, wet-dry stability
 - Good for cold weather applications
 - Provides multiple seals
- Cold joints/construction joints can be converted into water-tight working expansion joints


Epoxy injection

- Utilized for structural as well as nonstructural repairs

- Ideal for water seepage, control
- Environmentally friendly
- Temperature range: 32°F - 500°F
- Can be machine or hand injected

Expansion joint repairs

- Types of joints repaired
 - Architectural joints
 - Chemical resistant, pressure-containing joints
- Types of sealants used
 - Chemical resistant
 - Special formulations for joint applications
- Provides joint protection against:
 - Water damage
 - Environmental containment
 - Thermally induced joint movements
 - Freeze heave



Concrete Repair Services (CRS)

Deteriorating concrete structures can cause environmental as well as waste and disposal problems, increase shutdown or replacement costs, and create a safety hazard for employees.



A Team technician (above) cleans an EVA expansion joint prior to repair. Below, Team technicians complete repairs on the same expansion joint.



Concrete coatings, toppings


- Provides surface protection against chemicals, hazardous substances
 - Acids
 - Alcohols
 - Industrial solvents/chemicals
- Resistant, nonskid surfaces add safety factors for
 - Walking
 - Forklift traffic
 - Truck, vehicle traffic
- Site assessment, recommendation services available
- Various surface, topping colors available

Team Industrial Services

Concrete Repair Services (CRS)



Cracked and spalled tank base



Same tank base repaired and strengthened



Deteriorated pedestal for main support beam



Same pedestal restored and strengthened

Spall repairs

- Type of spalls repaired
 - Overhead
 - Vertical surface
 - Walls
 - Floors
- Site assessment, service provided
 - Repair procedure, materials are recommended
- Customer engineer is consulted for structural and critical repairs

Pump base, pedestal repairs

- Cost effective
- Types of repairs available
 - Structural repair
 - Structural upgrade
- Coatings available for added protection
 - Against corrosive atmospheres
 - Against chemicals



A deteriorated pump base



Spalled, cracked pedestal (left) is fully restored (right).




Same pump base repaired



Badly spalled floor area being prepared with a high strength repair material.

Concrete Repair Services (CRS)

Restore and strengthen deteriorating concrete structures with Team's state-of-the-art repair methods and materials.



Secondary containment repairs

- Required by federal, state and local regulation
- Prevents release of hazardous, toxic substances; reduces liability
- Saves plants regulatory reporting requirements
- Specialized repairs available
 - For existing concrete
 - To replace, install new chemical-resistant expansion joints
 - To plug or reroute drains
 - Coat containment with materials resistant to tank contents, service
- Crack repair applications
 - Floors
 - Drains
 - Walls

For Immediate Information Contact:

TEAM Industrial Services
 200 Hermann Dr., Alvin, TX 77511
 Phone: 281-331-6154 Fax: 281-331-4107